

CERAMIC CHIPS

TYPE	SHAPE	TRIANGLE	ANGLE CUT TRIANGLE	CYLINDER	ANGLE CUT CYLINDER	4-STAR	3-TRISTAR	ANGLE CUT TRISTAR	DOUBLE ANGLE CUT CYLINDER	ELLIPSE	ANGLE CUT ELLIPSE	ARROW HEAD	BALL	CONE	PYRAMID	
		G	GP	W	WP	SC	ST	STP	WPP	E	EP	GS	B	KC	TC	
AA	GRINDING	10x10;15x15; 20x20	10x10 15x15 20x20													
A		3x3; 4x4;6x6; 8x8; 10x10; 12x12; 15x15; 20x20; 25x25; 30x30	6x6; 8x8; 10x10; 12x12; 15x15; 20x20; 25x25; 30x30	4x10; 6x12; 8x10; 10x20; 15x20	6x12; 8x10; 10x20; 15x20	10x10; 20x10; 30x15; 30x30; 45x15	15x7; 15x15; 30x15; 30x25	15x7; 15x15; 30x15; 30x25	10, 12, 15, 18, 15	10x5x10; 15x7x15; 25x10x25	10x5x10; 15x7x15; 25x10x25	10x10; 15x10; 20x12		15x15; 30x30	38x38	
B		3x3; 4x4; 5x5; 6x6; 8x8; 10x10; 12x12; 15x15; 20x20; 25x25; 30x30; 35x35; 40x40	6x6; 8x8; 10x10; 12x12; 15x15; 20x20; 25x25; 30x30	4x10; 6x12; 8x10; 10x20; 15x20	3x15; 4x12; 6x12; 8x10; 10x20; 15x20	10x10; 20x10; 30x15; 30x30; 45x15	15x7; 15x15; 30x15; 30x25	15x7; 15x15; 30x15; 30x25	10, 12, 15, 18, 15	10x5x10; 10x5x12; 15x7x15; 25x10x25	10x5x10; 10x5x12; 15x7x15; 25x10x25	10x10; 15x10; 20x12	6; 8; 10	15x15; 30x30	38x38	
BD		12x12; 15x15; 20x20; 25x25; 30x30; 40x40	12x12; 15x15; 20x20; 25x25; 30x30	8x10; 10x20;	8x10; 10x20; 15x20	10x10; 20x10; 20x20; 45x15	15x7; 15x15; 30x15	15x7; 15x15; 30x15	10, 12, 15, 18, 15	10x5x10; 15x7x15; 25x10x25	10x5x10; 15x7x15; 25x10x25	10x10; 15x10; 20x12				
BC		8x8; 10x10; 15x15; 20x20	8x8; 10x10; 15x15; 20x20	4x10; 6x12; 8x10; 10x20; 15x20	6x12; 8x10; 10x20	10x10; 20x10; 20x20	15x7; 15x15	15x7; 15x15	10, 12, 15, 18, 15	10x5x10; 15x7x15; 25x10x25	10x5x10; 15x7x15; 25x10x25	10x10; 15x10; 20x12	4; 6; 8	15x15		
C		3x3; 4x4; 6x6; 10x10; 12x12; 15x15;	6x6		3x15; 4x12; 6x12; 8x10		15x7	15x7	10, 12, 15, 18, 15	10x5x10	10x5x10		6; 8			
G		3x3; 4x4; 5x5; 6x6; 8x8; 10x10; 12x12; 15x15	6x6; 8x8; 10x10; 12x12; 15x15	4x10; 6x12; 8x10;	3x6; 4x6;4x12; 6x12; 8x10; 10x8	10x10; 20x10	15x7; 15x15; 30x15; 30x25	15x7; 15x15; 30x15; 30x25	10, 12, 15, 18, 15	10x5x10; 15x7x15; 25x10x25	10x5x10; 15x7x15; 25x10x25	10x10; 15x10; 20x12	4; 6; 8; 10			
P		3x3; 4x4; 5x5; 6x6; 8x8; 10x10; 12x12; 15x15	6x6; 8x8; 10x10; 12x12; 15x15	4x10; 6x12; 8x10;	3x6;3x10;4x6; 4x12; 6x12; 8x10; 10x10; 12x12; 20x20	10x10; 20x10	15x7; 15x15	15x7; 15x15		10x5x10; 15x7x15	10x5x10; 15x7x15	10x10; 15x10; 20x12	4; 6; 8; 10			

ABRASIVE EFFICIENCY: ■ (strong grinding / rough processing)

■ (smoothing, polishing / finishing)

Main application of ceramic chips: deburring, rounding of sharp edges, scale removal, smoothing and surface homogenization, polishing. Recommended for steel (carbon, stainless, special types). We manufacture special types of chips for specific users' demand.

Order example: G 20x20 B: G - shape, 20x20 - size, B - type

